

Materials Not Included in Airworthiness Directive (AD) Docket

FAA-2004-19227-7

DMS Docket Number

2003-NM-95-AD

Directorate (Old) Docket Number, If Any

Airbus Service Bulletin A300-24-0099, R01, 12/18/03
 Airbus Service Bulletin A300-24-6082, R01, 12/18/03
 Airbus Service Bulletin 310-24-2088, R01, 12/18/03
 Thales Service Bulletin F11QY3121-24-003, 10/15/02
 Auxilec Service Bulletin F11QY3121-24-001, 2/2/98
 Auxilec Service Bulletin F11QY3121-24-002, 10/5/00
 Airbus Service Bulletin A300-24-0099, 10/11/02
 Airbus Service Bulletin A300-24-6082, 10/11/02
 Airbus Service Bulletin A310-24-2088, 10/11/02
 Thales Service Information Letter SIL F11QY3121-24-004, 7/11/01

Name/Description of Item(s) Not Included in DMS Docket and Maintained in the
 Supplemental AD Docket

MAY BE VIEWED AT: Federal Aviation Administration
 Transport Airplane Directorate
 Rules Docket
 1601 Lind Ave. SW.,
 Renton, WA 98055-4056
 425.227.1221

2004 OCT -6 A 10:55
 DEPT OF TRANSPORTATION
 CIVIL AVIATION
 DIVISION

DURING THE HOURS OF: 9 a.m. and 3 p.m., Monday through Friday,
 except Federal holidays.